


1 2 3 4 5



Part	Value	Footprint	Notes
R81	10k		
R82	10k		
R83	4k7		
R84	4k7		
R85	15k		
R86	15k		
R87	10k		
R88	10k		
R89	10k		
R90	10k		
R91	10k		
R92	10k		
R93	10k		
R94	10k		
R95	10k		
R96	10k		
R97	10k		
R98	10k		
R99	10k		
R100	10k		
R101	10k		
R102	10k		
R103	10k		
C101	100pF		
C102	100pF		
C103	100pF		
C104	100pF		
C105	100pF		
C106	100pF		
C107	100pF		
C108	100pF		
C109	100pF		
C110	100pF		
C111	100pF		
C112	100pF		
C113	100pF		
C114	100pF		
C115	100pF		
C116	100pF		
C117	100pF		
C118	100pF		
C119	100pF		
C120	100pF		
C121	100pF		
C122	100pF		
C123	100pF		
C124	100pF		
C125	100pF		
C126	100pF		
C127	100pF		
C128	100pF		
C129	100pF		
C130	100pF		
C131	100pF		
C132	100pF		
C133	100pF		
C134	100pF		
C135	100pF		
C136	100pF		
C137	100pF		
C138	100pF		
C139	100pF		
C140	100pF		
C141	100pF		
C142	100pF		
C143	100pF		
C144	100pF		